


AUTOPILOT/FLIGHT DIRECTOR WARNING AND ANNUNCIATION

BOEING
767
PARTS CATALOG (MAINTENANCE)



V 22140102 REV 329

PANEL INSTL-PILOTS MAIN (AUTOPILOT/FLIGHT DIRECTOR WARNING AND ANNUNCIATION ONLY)

FIGURE 2

22-14-01-02

HXL
AUG 22/08

22-14-01-02
PAGE 0

BOEING
 767
PARTS CATALOG (MAINTENANCE)

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
2			PANEL INSTL-PILOTS MAIN (AUTOPILOT/FLIGHT DIRECTOR WARNING AND ANNUNCIATION ONLY)		
- 1	233T2100-1		PANEL INSTL-PILOTS MAIN (AUTOPILOT/FLIGHT DIRECTOR WARNING AND ANNUNCIATION ONLY) VARIABLE DRAWING REF: 233T2100-5048 FOR NHA/OTHER SYS DET SEE: 25-10-00-03		RF
5	622-5374-002		.ANNUNCIATOR-AUTO. LDG STATUS SUPPLIER CODE: V4V792 SPECIFICATION NUMBER: S241T120-1 ELECTRICAL EQUIP NUMBER: N00070 N00071 COMPONENT MAINT MANUAL REF: 22-14-70		2
10	754-0511-001		..PANEL-EDGELIT SUPPLIER CODE: V13499		1
15	G42-22		...FASTENER-COLLAR SUPPLIER CODE: V06097		2
- 20	G42SCREWBROWN		ATTACHING PARTS ...FASTENER-CPTV SCR SUPPLIER CODE: V06097 -----*-----		2
25	MS90451-7132		...LAMP-		5
- 52	233T2222-58		.PANEL ASSY-2 CREW CONT STATIC SENSITIVE PART P1-3		RF
55	123-10D		..CLAMP- SUPPLIER CODE: V33463		1
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					

- ITEM NOT ILLUSTRATED

HXL

22-14-01-02

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details.

22-14-01
 FIG. 02
 PAGE 1
 DEC 22/07



767

PARTS CATALOG (MAINTENANCE)

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
2					
60	BCREF6229		..LIGHT ASSY-AUTOPILOT IND SUPPLIER CODE: V81590 OVERLENGTH PART NUMBER: 434-674-1005-1226 SPECIFICATION NUMBER: S231T300-1226 ELECTRICAL EQUIP NUMBER: L00019 OPTIONAL PART: BCREF8565 V81590 FOR DETAILS SEE: 33-16-02-02		1
60	BCREF8565		..LIGHT ASSY-AUTOPILOT IND SUPPLIER CODE: V81590 OVERLENGTH PART NUMBER: 434-674-1031-2226 SPECIFICATION NUMBER: S231T300-2226 ELECTRICAL EQUIP NUMBER: L00019 OPTIONAL PART: BCREF6229 V81590 FOR DETAILS SEE: 33-16-02-03		1
- 104	233T2223-120		.PANEL ASSY-2 CREW CONT P3-1 PRE ALERT SB: 33A0087		RF
- 107	233T2223-1120		.PANEL ASSY-2 CREW CONT P3-1 POST ALERT SB: 33A0087		RF
110	123-10D		..CLAMP- SUPPLIER CODE: V33463		1
- 600	286T0011-106		WIRE BUNDLE ASSY-		RF
- 605	286T0031-107		WIRE BUNDLE ASSY-		RF
610	BACC45FT12A12S		.CONNECTOR- ELECTRICAL EQUIP NUMBER: D00633 D00635 WIRING DIAGRAM REF: 221411 221421		1
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					

- ITEM NOT ILLUSTRATED

HXL

22-14-01-02

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details.

22-14-01
FIG. 02
PAGE 2
DEC 22/07

BOEING
 767
PARTS CATALOG (MAINTENANCE)

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
2 615	BACC45FT14A15S		.CONNECTOR- ELECTRICAL EQUIP NUMBER: D01363 D01365 WIRING DIAGRAM REF: 221411 221421		1
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					

— ITEM NOT ILLUSTRATED

HXL

22-14-01-02

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details.

22-14-01
 FIG. 02
 PAGE 3
 DEC 22/07