

PITOT STATIC PROBE ANTI-ICING



PANEL INSTL-OVHD (PITOT STATIC PROBE ANTI-ICING ONLY)
FIGURE 2

HXL
DEC 22/07

30-31-01-02

30-31-01-02
PAGE 0

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details.

BOEING
 767
PARTS CATALOG (MAINTENANCE)

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
2			PANEL INSTL-OVHD (PITOT STATIC PROBE ANTI-ICING ONLY)		
- 1	233T3100-1		PANEL INSTL-OVHD (PITOT STATIC PROBE ANTI-ICING ONLY) VARIABLE DRAWING REF: 233T3100-5048 FOR NHA/OTHER SYS DET SEE: 25-10-00-03		RF
5	233T3233-14		.PANEL ASSY-MISC ANN SUPPLIER CODE: V89954 ELECTRICAL EQUIP NUMBER: M10394 COMPONENT MAINT MANUAL REF: 33-16-52		RF
7	233T3233-35		.PANEL ASSY-MISC ANN SUPPLIER CODE: V89954 ELECTRICAL EQUIP NUMBER: M10394 COMPONENT MAINT MANUAL REF: 33-16-52 POST AIRLINE MOD: MT0-310236 VSAS		RF
10	BCREF6125		..LIGHT ASSY-CAPT PITOT IND SUPPLIER CODE: V81590 OVERLENGTH PART NUMBER: 434-674-1005-1259 SPECIFICATION NUMBER: S231T300-1259 OPTIONAL PART: BCREF8579 V81590 FOR DETAILS SEE: 33-16-02-02		1
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					

- ITEM NOT ILLUSTRATED

HXL

30-31-01-02

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details.

30-31-01
 FIG. 02
 PAGE 1
 DEC 22/07



767

PARTS CATALOG (MAINTENANCE)

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
2					
10	BCREF8579		..LIGHT ASSY-CAPT PITOT IND SUPPLIER CODE: V81590 OVERLENGTH PART NUMBER: 434-674-1031-2259 SPECIFICATION NUMBER: S231T300-2259 OPTIONAL PART: BCREF6125 V81590 FOR DETAILS SEE: 33-16-02-03		1
15	BCREF6126		..LIGHT ASSY-F/O PITOT IND SUPPLIER CODE: V81590 OVERLENGTH PART NUMBER: 434-674-1005-1260 SPECIFICATION NUMBER: S231T300-1260 OPTIONAL PART: BCREF8580 V81590 FOR DETAILS SEE: 33-16-02-02		1
15	BCREF8580		..LIGHT ASSY-F/O PITOT IND SUPPLIER CODE: V81590 OVERLENGTH PART NUMBER: 434-674-1031-2260 SPECIFICATION NUMBER: S231T300-2260 OPTIONAL PART: BCREF6126 V81590 FOR DETAILS SEE: 33-16-02-03		1
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					

— ITEM NOT ILLUSTRATED

HXL

30-31-01-02

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details.

30-31-01
FIG. 02
PAGE 2
DEC 22/07



767

PARTS CATALOG (MAINTENANCE)

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
2					
20	BCREF6127		..LIGHT ASSY-AUX PITOT IND SUPPLIER CODE: V81590 POSITION DATA: L OVERLENGTH PART NUMBER: 434-674-1005-1261 SPECIFICATION NUMBER: S231T300-1261 OPTIONAL PART: BCREF8581 V81590 FOR DETAILS SEE: 33-16-02-02		1
20	BCREF8581		..LIGHT ASSY-AUX PITOT IND SUPPLIER CODE: V81590 POSITION DATA: L OVERLENGTH PART NUMBER: 434-674-1031-2261 SPECIFICATION NUMBER: S231T300-2261 OPTIONAL PART: BCREF6127 V81590 FOR DETAILS SEE: 33-16-02-03		1
25	BCREF6128		..LIGHT ASSY-AUX PITOT IND SUPPLIER CODE: V81590 POSITION DATA: R OVERLENGTH PART NUMBER: 434-674-1005-1262 SPECIFICATION NUMBER: S231T300-1262 OPTIONAL PART: BCREF8582 V81590 FOR DETAILS SEE: 33-16-02-02		1
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					

— ITEM NOT ILLUSTRATED

HXL

30-31-01-02

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details.

30-31-01
FIG. 02
PAGE 3
DEC 22/07



767 PARTS CATALOG (MAINTENANCE)

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
2					
25	BCREF8582		..LIGHT ASSY-AUX PITOT IND SUPPLIER CODE: V81590 POSITION DATA: R OVERLENGTH PART NUMBER: 434-674-1031-2262 SPECIFICATION NUMBER: S231T300-2262 OPTIONAL PART: BCREF6128 V81590 FOR DETAILS SEE: 33-16-02-03		1
30	BACC45FN14-15P		..CONNECTOR		1
35	BACC45FN14-15P7		..CONNECTOR		1
40	BACC45FN14-15P9		..CONNECTOR		1
			ATTACHING PARTS		
- 45	NAS1801-04-5		..SCREW-		6
- 50	K19798-04		..NUT SUPPLIER CODE: V15653 SPECIFICATION NUMBER: BACN10NW1 OPTIONAL PART: RMA4812-160-40 V72962 293162 V60119 -----*-----		6
- 200	286T0062-300		WIRE BUNDLE ASSY-		RF
205	BACC45FT14A15S7		.CONNECTOR- ELECTRICAL EQUIP NUMBER: D01678 WIRING DIAGRAM REF: 527111		1
- 250	286T0066-300		WIRE BUNDLE ASSY-		RF
255	BACC45FT14A15S		.CONNECTOR- ELECTRICAL EQUIP NUMBER: D02888 WIRING DIAGRAM REF: 303211		1
- 300	286T0070-300		WIRE BUNDLE ASSY-		RF
305	BACC45FT14A15S9		.CONNECTOR- ELECTRICAL EQUIP NUMBER: D02890 WIRING DIAGRAM REF: 271112		1
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					


- ITEM NOT ILLUSTRATED

HXL

30-31-01-02

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details.

30-31-01
FIG. 02
PAGE 4
DEC 22/07



V 30315102 SHT 1 REV 167

EQUIPMENT ASSY-P33 MISC ELEC PNL FWD (PITOT STATIC PROBE ANTI-ICING ONLY)
FIGURE 2 (SHEET 1)


FIGURE 2 (SHEET 1)

30-31-51-02

HXL
DEC 22/06

30-31-51-02
PAGE 0

BOEING
767
PARTS CATALOG (MAINTENANCE)



V 30315102 SHT 2 REV 162

EQUIPMENT ASSY-P33 MISC ELEC PNL FWD (PITOT STATIC PROBE ANTI-ICING ONLY)
FIGURE 2 (SHEET 2)

30-31-51-02

HXL
DEC 22/06

30-31-51-02
PAGE 0A

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details.

BOEING
 767
PARTS CATALOG (MAINTENANCE)

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
2			EQUIPMENT ASSY-P33 MISC ELEC PNL FWD (PITOT STATIC PROBE ANTI-ICING ONLY)		
- 9	284T0189-155		EQUIPMENT ASSY-P33 MISC ELEC PNL (PITOT STATIC PROBE ANTI-ICING ONLY) POSITION DATA: FWD FOR NHA/OTHER SYS DET SEE: 25-50-51-01	163999	RF
- 12	284T0189-183		EQUIPMENT ASSY-P33 MISC ELEC PNL (PITOT STATIC PROBE ANTI-ICING ONLY) POSITION DATA: FWD FOR NHA/OTHER SYS DET SEE: 25-50-51-01	155162	RF
24	BAC27TEX4206		.DECALSET-INCLUDES DECALS IDENTIFIED ON THE ILLUSTRATION		RF
25	BAC27TEX4203		.DECALSET-INCLUDES DECALS IDENTIFIED ON THE ILLUSTRATION		RF
30	BAC27TEX4201		.DECALSET-INCLUDES DECALS IDENTIFIED ON THE ILLUSTRATION		RF
50	770-540-1		.RELAY- SUPPLIER CODE: VF0553 ELECTRICAL EQUIP NUMBER: K00241 K00243 K00310 K00312		4
50	770-540-2		.RELAY- SUPPLIER CODE: VF0553 ELECTRICAL EQUIP NUMBER: K00241 K00243 K00310 K00312		4
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					

- ITEM NOT ILLUSTRATED

HXL

30-31-51-02

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details.

30-31-51
 FIG. 02
 PAGE 1
 DEC 22/08



767

PARTS CATALOG (MAINTENANCE)

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7 NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
2				
50	770540-2	.RELAY- SUPPLIER CODE: VF5341 ELECTRICAL EQUIP NUMBER: K00241 K00243 K00310 K00312		4
55	E410-1537	.RELAY- SUPPLIER CODE: V99699 SPECIFICATION NUMBER: BACR13CG2A OPTIONAL PART: E415-1078 V99699 BR230S0116 V56623 KD4A017 V58687 FCA410-62 V78290 ELECTRICAL EQUIP NUMBER: K00643 K00644 K00645 K00646		4
- 200	286T0144-300	.WIRE BUNDLE ASSY		RF
205	000300-1560	..SOCKET- SUPPLIER CODE: V05574 ELECTRICAL EQUIP NUMBER: D03948 D03952 WIRING DIAGRAM REF: 303111 303013		2
210	BACS16W1	..SOCKET- ELECTRICAL EQUIP NUMBER: D10186 D10188 WIRING DIAGRAM REF: 303111 303121		2
- 250	286T0142-300	.WIRE BUNDLE ASSY-		RF
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE				

- ITEM NOT ILLUSTRATED

HXL

30-31-51-02

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details.

30-31-51
FIG. 02
PAGE 2
DEC 22/08



767

PARTS CATALOG (MAINTENANCE)

FIG ITEM	PART NUMBER	1 2 3 4 5 6 7	NOMENCLATURE	EFFECT FROM TO	UNITS PER ASSY
2					
- 253	289T1065-10106		..TAPE-IDENT PLACARD CONTENT: D10184 M/W K00643 POST ALERT SB: 27A0160		1
255	000300-1560		..SOCKET- SUPPLIER CODE: V05574 ELECTRICAL EQUIP NUMBER: D03910 D03938 WIRING DIAGRAM REF: 303121		2
260	BACS16W1		..SOCKET- ELECTRICAL EQUIP NUMBER: D10184 D10190 WIRING DIAGRAM REF: 303111 303121		2
ILLUSTRATION ITEMS NOT ON PARTS LIST ARE NOT APPLICABLE					

- ITEM NOT ILLUSTRATED

HXL

30-31-51-02

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details.

30-31-51
FIG. 02
PAGE 3
DEC 22/08