



Tel: +44 (0)1394 380307
Fax: +44 (0)1394 385156
email: chris@lindos.co.uk

Saddlemakers Lane, Melton, Woodbridge, Suffolk IP12 1PP U.K.

LA100 Application Note 6 – Upgrading units with the latest software.

To establish the type of upgrade required you must first know the serial number of your LA100. The serial number is displayed at the bottom left of the startup screen. It is also on the EPROM label and on the top front right of the chassis.

To use the latest software in units with serial numbers less than 100 (and also provide non-volatile results memory), UPG1 or UPG2 is necessary – UPG1 is the recommended upgrade. Once upgraded, units with serial number less than 399 have 1000 added to their original serial number. For units with serial numbers greater than 399, the latest software can be installed directly by replacing the EPROMS with new ones supplied by Lindos free of charge upon request. The serial numbers of such units remain unchanged.

Compatibility with new software

All upgraded units will be compatible with all current and future software.

WAB 19 Apr 1989