Mitutoyo

—ユーザーズマニュアルー

グラプレート用 標準鋼製スタンド・落下防止付きスタンド キャスター付きスタンド

マニュアル No.99MBF003①

【はじめに】

このたびはグラプレート用標準鋼製スタンド・落下防止付きスタンド・キャスター付きスタンドをご購入いただ き誠にありがとうございます。


- この「ユーザーズマニュアル」はグラプレートの使用上の注意事項について記載してあります。定盤の性 能を十分に発揮させ、効果的にご使用いただくために、この「ユーザーズマニュアル」を最後までお読
- お読みになった後も必ずスタンドの近くに保管し、常時参照できるようにして下さい。
- スタンドの使用によって生じた逸失利益につきましては、弊社は一切その責任を負いかねます。
- 本書の記載内容については、将来予告なく変更することがあります。

【安全に関する注意】


スタンドの性能を十分に発揮し、安全に作業するために、以下の記述の点にご注意下さい。これら の事項に従わなかった為に生じた事故や故障について、弊社は一切責任を負いかねます。

- 本スタンドは、グラプレートの設置を目的に作られたものです。グラプレートの設置以外の目的では使用 しないで下さい。
- 不要な物を置かないようにして下さい。
- 測定時及び移設時は、落下防止プレートやキャスターには触れないで下さい。手を挟むなどケガをする 恐れがあります。
- 強い衝撃を与えないで下さい。
- 作業者の服装、特に履物にご注意下さい。スリッパの使用は厳禁です。安全靴を使用して下さい。

③ 専用鋼製スタンド上の支持脚の中心位置と、グラプレート下面に接着されている脚受けの中心位置が 合うように設置して下さい。



※調整ボルトを回転させて高さ調整を 行って下さい。



※ 410 穴を使用し支持脚を回転させて 高さ調整を行って下さい。

小型専用鋼製スタンド

④ 使用面に水準器を置き、3 点の支持脚高さを調整しながら、グラプレート使用面の水平出しを行います。 完了後、固定ナットを締め付けて下さい。補助足のあるグラプレートについては、水平出しのあと補助足 をグラプレート下面に軽く当てて下さい。強く当てると使用面精度に影響しますのでご注意下さい。

《キャスター付きスタンドを用いた設置方法》

① 床にスタンドを設置します。調整ボルトを使用してキャスターを浮かせて、スタンドが移動しないように固 定してから作業を行って下さい。

キャスター付きスタンドを設置する場合は必ず調整ボルトを調節し、スタンドが移動しないように固定 <u>警告</u> してから作業を行って下さい。


- ② 落下防止プレートを全て外します。(M10 ネジ2本によって固定されています。)
- ③ グラプレートをスタンドの上にクレーンなどを使って設置し、水平出しを行います。(作業の詳細は、標準 鋼製スタンドを参照のこと。)
- ④ 外した M10 ネジ2 本で落下防止プレートを取付けます。
- ⑤ グラプレートと落下防止プレートの隙間が 10mm 以下となるように位置を調整して下さい。隙間が大きい と指などを挟み、ケガをする恐れがあります。

√ 落下防止プレートとグラプレートとの隙間に測定物や指が入らないよう十分にご注意下さい。万が一 グラプレートが動いた時に、破損や指を挟むなどしてケガをする恐れがあります。

【グラプレートの据え付け】

グラプレート及び専用鋼製スタンドの設置場所は、十分耐力のある基礎上を選んでください。 《標準鋼製スタンド・落下防止付きスタンドを用いた設置方法》

① 床にスタンドを設置します。その際 4 点の脚がガタつなかいよう調整ボルトで調節して下さい。



② グラプレートをスタンドの上にクレーンなどを使って設置します。

✓! グラプレート表面は非常に滑りやすいので、設置作業は十分に気をつけて行って下さい。

落下防止付きスタンドにグラプレートを設置する場合は、グラプレートと落下防止プレートが接触しない ように、慎重に作業を行って下さい。

✓ グラプレートと落下防止プレートが衝突すると、破損などによりケガをする恐れがありますので、設置

グラプレートと落下防止プレートの隙間が 10mm 以下となるように位置を調整して下さい。隙間が大きい と指などを挟み、ケガをする恐れがあります。

↑ 落下防止プレートとグラプレートとの隙間に測定物や指が入らないよう十分にご注意下さい。 万が一 <u>グラプレートが動いた時に、破損や指を挟むなどしてケガをする恐れがあります。</u>

【キャスター付きスタンドの移設作業方法】

①グラプレートに何も載っていないことを確認します。

測定物をグラプレートに載せたまま移動させることは極めて危険です。必ず、別々に移動させてくだ。 警告_さい。

②4ヶ所の調整ボルトを緩め、キャスターが動く状態にします。

キャスターには触らないようにして下さい。ケガをする恐れがあります


③落下防止プレートとグラプレートの隙間が 10mm 以内にあるか確認し、グラプレートを移設します。

移設の際にグラプレートがずれる場合があります。危険防止のためにも落下防止プレートとグラプレ ◆ 移設の除にクノノレートル・メ 4 いる物 ロル・のフェ フ。 たに トレートを持っての移設は絶対に行わないで下さ ートの隙間は最小にして下さい。また、落下防止プレートを持っての移設は絶対に行わないで下さ 警告 い。手を挟むなどケガをする恐れがあり大変危険です。

④4つの調整ボルトで、スタンドががたつかないように固定して下さい。

⑤水平出しを行います。

【仕様】



ユードNo.			サイズ(mm)			高さ	グラプレート質量
標準鋼製スタンド	落下防止付き	キャスタ付き	$A \times B \times H$	K	L	h(mm)	(kg)
517-203	517-203R	517-203CR	$600 \times 450 \times 100$	370	500	$755 \sim 775$	80
517-204	517-204R	517-204CR	$600 \times 600 \times 130$	500	500	$755 \sim 775$	140
517-205	517-205R	517-205CR	$750 \times 500 \times 130$	420	630	$755 \sim 775$	146
517-206	517-206R	517-206CR	$1000 \times 750 \times 150$	630	700	$755 \sim 775$	337
517-207	517-207R	517-207CR	$1000 \times 1000 \times 150$	700	700	$755 \sim 775$	450
517-208	517-208R	517-208CR	$1500 \times 1000 \times 200$	700	1100	$755 \sim 775$	900
517-209	517-209R	517-209CR	$2000 \times 1000 \times 250$	600	1500	$755 \sim 775$	1,500
517-210	517-210R	517-210CR	$2000 \times 1500 \times 300$	1100	1500	$755 \sim 775$	2,700

《付属品》・・・ユーザーズマニュアル(本書) 1部

Mitutoyo

— User's Manual —

Standard Steel Stand, Drop Prevention Stand, and Caster Wheel Stand for Graplate (Precision Granite Surface Plate)

[Foreword]


Thank you very much for purchasing our standard steel stand, drop prevention stand, or caster wheel stand for the granite surface plate.

- This User's Manual provides notes on using the granite surface plate. To effectively use and maximize the performance of the plate, read through this manual.
- After reading this manual, always keep it near the stand so that you can refer to it anytime.
- Note that we bear no responsibility for financial loss caused by using this stand.
- The contents of this manual are subject to change without notice.

Safety Precautions


To maximize the stand performance and work safely, note the following. We bear no responsibility for any accident or failure caused by breaking these rules.

- This stand is designed for installing the granite surface plate. Do not use it for other purposes.
- Do not put unnecessary items on this stand.
- Do not touch the drop prevention plate or caster wheel during measurement or relocation. You could catch your hand in it or otherwise get injured.
- Do not shake the stand.
- The operator must wear carefully chosen clothes, especially shoes. Never wear slippers. Wear safety shoes
- 3 Align the centers of the support feet on the dedicated steel stand and the foot rests glued to the bottom surface of the granite surface plate



Dedicated steel stand for large scale

* Rotate the adjusting bolt and adjust height.



Dedicated steel stand for small scale

- * Rotate the supporting leg by using the
 - ϕ 10 hole and adjust height.
- ④ Put a level on the working face of the granite surface plate and level the face by adjusting the height of the three support feet. After leveling the face, tighten the fixing nuts. If you are installing a granite surface plate that requires auxiliary feet, lightly push them against the bottom surface of the plate. Do not strongly push them because this will change the accuracy of the working face.

(When using the caster wheel stand for installation)

① Install the stand on the floor. Keep the caster wheels off the ground by using adjusting bolts so the stand does not move.



Be sure to fix the stand in place by using the adjusting bolts before installing the caster wheel stand.

- ② Remove all drop prevention plates. (They are fixed in place with two M10 screws.)
- 3 Install the granite surface plate onto the stand by using a crane or other machine and then set and level the beam. (For details, see the procedure for the standard steel stand above.).
- ④ Install the drop prevention plates by using the two M10 screws removed in step (2) above.
- ⑤ Position the granite surface plate and the drop prevention plate so that the gap between them is 10 mm or less. If the gap is larger, you could catch your finger in it or get injured.




Be careful not to insert a workpiece or finger between the drop prevention plate and granite surface plate. If the granite surface plate moves, the workpiece might be broken or you could catch your finger between the plates or get injured.

[Installing The Graplate]

Install the granite surface plate and its dedicated steel stand on a sufficiently resistant foundation.

(When using the standard steel stand or drop prevention stand for installation)

① Install the stand on the floor. Adjust the foot height using the adjusting bolts so that the four feet do not



② Install the granite surface plate onto the stand by using a crane or other machine.



Because the surface of the granite surface plate is very slippery, be extremely careful when installing the plate.

When installing the granite surface plate onto the drop prevention stand, be careful not to allow the plate to contact the drop prevention plate.



If the granite surface plate and drop prevention plate collide, a breakage or other problem might result

Position the granite surface plate and drop prevention plate so that the gap between them is 10 mm or less. If the gap is larger, you could catch your finger in it or get injured.



Be careful not to insert a workpiece or finger between the drop prevention plate and granite surface plate. If the granite surface plate moves, the workpiece might be broken or you could catch your finger between the plates or get injured.

[Moving The Caster Wheel Stand]

① Make sure that there are no items on the granite surface plate.



Always move the granite surface plate and workpieces separately. Moving a plate on which a workpiece sits is extremely dangerous.

② Loosen the four adjusting bolts to allow the caster wheels to move.




Do not touch the caster wheels. Doing so might cause an injury.

3 Make sure that the gap between the drop prevention plate and the granite surface plate is within 10 mm, and then move the granite surface plate.



The granite surface plate might shift during relocation. Minimize the gap between the drop prevention plate and granite surface plate to ensure safety. Never move the granite surface plate while holding the drop prevention plate. This is extremely dangerous because you could catch your hand between them or otherwise get injured.

- ④ Fix the stand in place by using the four adjusting bolts to prevent rattling.
- (5) Set and level the beam



Code No.			Dimensions of Graplate (mm)			Height	Weight of		
Standard Steel	Drop	Caster Wheel	A×B×H	A×B×H K L		_		h(mm)	Graplate
Stand	Prevention	Stand	A^D^II	K	L	11(111111)	(kg)		
517-203	517-203R	517-203CR	600×450×100	370	500	755 ~ 775	80		
517-204	517-204R	517-204CR	600×600×130	500	500	755 ~ 775	140		
517-205	517-205R	517-205CR	750×500×130	420	630	755 ~ 775	146		
517-206	517-206R	517-206CR	1000×750×150	630	700	755 ~ 775	337		
517-207	517-207R	517-207CR	1000×1000×150	700	700	755 ~ 775	450		
517-208	517-208R	517-208CR	1500×1000×200	700	1100	755 ~ 775	900		
517-209	517-209R	517-209CR	2000×1000×250	600	1500	755 ~ 775	1,500		
517-210	517-210R	517-210CR	2000×1500×300	1100	1500	755 ~ 775	2.700		

《Accessory》 User's Manual (1 PC.)