
Model: Iris/Lilac 3bin Sorter			Date: 11-Dec-01		1	No.: MA849001	
Modified Article: Antistatic Brush			Prepared by: M.Tsuyuki				
From: Technical Services Dept., GTS Division							
Reason for	☐ Parts catalog correction	☐ Vendor change ☐ To improve reliability		ange	☐ To m	neet standards	
Modification:	☐ To facilitate assembly			()		
	☐ Part standardization	Othe	r				

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
AA120027	A8491661	Antistatic Brush	4	X/O	7 9 11	15 24 3	


The Antistatic Brush has been modified so that the fibers remain firmly attached to the brush, which will ensure that SC410 is not triggered when paper is re-fed from the bypass tray to print the 2nd side.

3. VERTICAL TRANSPORT (A849)

4. TRANSPORT AND DRIVE SECTION 1 (A849)









Modification Bulletin

PAGE: 2/2

Model: Iris/Lilac 3bin Sorter Date: 11-Dec-01 No.: MA849001

RCL (Japan) Production

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NO.
CS160	120,	USA, Canada.	A849-17	H0510500001
	220-240V,	South America		
	/50,60Hz	Europe, etc		
CS160	120,	Europe, etc.	A849-26	From Next
	220-240V,			Production
	/50,60Hz			
CS160	220-240V,	USA, Canada.	A849-55	L0431080001
	/50,60Hz	Europe, etc		