RIGOH

Technical Bulletin

PAGE: 1/1

Reissued: 30-Apr-99

Model: F401/411/421/C-Bird	Date: 15-Apr-99	No.: RA175012a
----------------------------	-----------------	----------------

RTB Correction

The items (cut-in serial number) in bold italics have been corrected.

· · · · · · · · · · · · · · · · · · ·	,			
Subject: DJF So	ftware Modification History		Prepared	by: F. Noguchi
From: Technical	Service Dept., GTS Division			
Classification:	☐ Troubleshooting	☐ Part informa	tion [Action required
	☐ Mechanical	Electrical	[Service manual revision
	☐ Paper path	☐ Transmit/red	eive [Retrofit information
	Other ()			

DJF modifications and history are as follows.

Main ROM(A6105820) modification history

Suffix	Description	Cut-in Serial Number
С	This ROM was used from the first production run.	A610-15: A16060001
		A610-17: A7146060001
		A610-22: AB86060001
		A610-26: J90660001
D	To prevent original jams:	Not implemented
	In the limitless mode, if a new original is fed while the	
	paper trays are being switched, a jam will occur.	
E	This version is the same as that of "C".	A610-15: 6A16120001
	Notes	A610-17: A7146110001
	A software change will not prevent original jams in the	A610-22: AB87010001
	limitless mode if a new original is fed while the paper	A610-26: 3J90170001
	trays are being switched.	
	Since the occurrence rate of this problem is extremely	
	low, this is being treated as a product limitation.	1010.15.011000001
F	Standardization with the Penguin series	A610-15: 6A18030001
		A610-17: A714803000
		A610-22: AB88030001 A610-26: 3J90680001
G	To many and the following much large when the O in Amenda	
G	To prevent the following problems when the 2 in 1 mode is used:	A610-15: 6A18060001 A610-17: A7148060001
	The machine stops (but the print key remains red) after	A610-17: A7148060001 A610-22: AB88060001
	the job if the number of originals and the number	A610-22: AB66060001 A610-26: 3J90680001
	input on the main unit differ.	A010-20. 3390080001
	After an odd number of originals is used, the image in	
	the next copy job is elongated or a paper jam	
	occurs.	
Н	To prevent original non-feed out in European version	A610-15: 6A18100001
	main frame machines:	A610-17: A7148100001
	Due to the difference in the feed-in and feed-out timing	A610-22: AB88100001
	for the B6Y size paper, three originals will be set on the	A610-26: 3J91080001
	exposure glass at the same time as opposed to two.	