

Model: Bellini		Date: 19-Oct-00	No.: MA294051
Modified Article: I/F Board Fuse		Prepared by: J. Mochizuki	
From: Technical Services Dept., GTS Division			
Reason for Modification:	<input checked="" type="checkbox"/> Parts catalog correction	<input type="checkbox"/> Vendor change	<input type="checkbox"/> To meet standards ()
	<input type="checkbox"/> To facilitate assembly	<input type="checkbox"/> To improve reliability	
	<input type="checkbox"/> Part standardization	<input type="checkbox"/> Other	

The fuse (FU101) on the optional interface board has been registered as a service part. Please add the following item to the Interface Board Type 850 (B327) parts catalog.

Incorrect part number	Correct part number	Description	Q'ty	Int	Page	Index	Note
	11070719	Fuse – K19371/1A	1		3	*3	

*: New Index

