

Reissued: 31-Jan-01

|                                      |                 |                |
|--------------------------------------|-----------------|----------------|
| Model: Iris/Lilac2 Controller RC-210 | Date: 30-Jan-01 | No.: MG549001a |
|--------------------------------------|-----------------|----------------|

## MB Correction

The items in bold italics have been corrected or added.

|  |  |   |  |
|--|--|---|--|
| Modified Article: Parts Catalog              |  | Prepared by: M. Tsuyuki                         |  |
| From: Technical Services Dept., GTS Division |  |   |  |
| Reason for Modification:                     | <input checked="" type="checkbox"/> Parts catalog correction | <input type="checkbox"/> Vendor change          | <input type="checkbox"/> To meet standards ( ) |
|  | <input type="checkbox"/> To facilitate assembly              | <input type="checkbox"/> To improve reliability |  |
|  | <input type="checkbox"/> Part standardization                | <input type="checkbox"/> Other                  |  |

| Old part number        | New part number | Description      | Q'ty | Int | Page | Index | Note |
|------------------------|-----------------|------------------|------|-----|------|-------|------|
| G6785818               |                 | Control Board    | 1→0  |     | 3    | 2     |      |
| <b><i>G5495400</i></b> |                 | ASIC – Eagle2    | 1    |     | 3    | 4     |      |
|                        | G5495651        | Controller Board |      |     |      |       |      |
|                        | G5495102        | DIMM R-PS2 4MB   | 0→1  |     | 3    | 11    |      |

Please correct your parts catalog.

