

Model: Russian-C2 Printer/Scanner Cont. Type 1027		Date: 27-Jun-02	No.: MB461001
Modified Article: Operating instructions		Prepared by: S. Tomoe	
From: Technical Services sec. Service Planning Dept.			
Reason for Modification:	☒ Parts catalog correction	☐ Vendor change	☐ To meet standards ()
	☐ To facilitate assembly	☐ To improve reliability	
	☐ Part standardization	☐ Other	

The Printer Reference Guide has been registered as a service part.

New part number	Description	Q'ty	Page	Index	Note
B4618607	Operating Instruction – Printer Reference 1	1	3	16	

Reissued: 11-Nov-03

Model: Russian-C2 Printer/Scanner Cont. Type 1027	Date: 30-Oct-03	No.: MB461002a
---	-----------------	----------------

MB Correction

The items in bold italics have been corrected or added.

Modified Article: Network Interface Board		Prepared by: Y. Ohtani	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction	☐ Vendor change	☐ To meet standards ()
	☐ To facilitate assembly	☐ To improve reliability	
	☐ Part standardization	☒ Other	

Due to a firmware version change, the Network Interface Board has been changed.

The P/N change below is a Parts Catalog correction, as G3355800 is the P/N for the Japan domestic model while G3355817 is for all other models (which has been used since the beginning of mass production). The separate P/N is due to a difference in firmware.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G3355800	G3355817	Network Interface Board	1	X/O	2	9	

Model: Russian-C2 Printer/Scanner Cont. Type 1027		Date: 26-Apr-04	No.: MB461003
Modified Article: Parts Catalog Correction		Prepared by: Y. Ohtani	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☒ Other	☐ To meet standards ()

The DIMM have been changed for use on the European model.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B453 5117	B453 5118	Printer/Scanner ROM DIMM	1	X/O	3	8	
B461 5117	B461 5118	Printer ROM DIMM	1	X/O	3	8	

Model: Russian-C2 Printer/Scanner Cont. Type 1027		Date: 26-Apr-04	No.: MB461004
Modified Article: Parts Catalog Correction		Prepared by: Y. Ohtani	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☒ Other	☐ To meet standards ()

The following have been changed in accordance with the release of Printer System firmware v2.04.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B453 5118	B505 5117	Printer ROM Dimm	1	X/O	3	8	
B461 5118	B506 5117	Printer ROM Dimm	1	X/O	3	8	

[Japan Production]

MODEL NAME	DESTINATION	CODE	SERIAL NO.
Printer/Scanner Controller Type 1027	USA	B453-10	J07309xxxxx
	USA, Europe	B453-14	L121309xxxx
	USA	B453-15	J07309xxxxx
	USA, Asia	B453-17	J0730800001
	Europe	B453-22	J07309xxxxx
	Europe	B453-24	L121309xxxx
	Europe	B453-26	4N1093xxxx
	Europe, etc	B453-27	J07309xxxxx
Printer Controller Type 1027	USA	B461-10	J08310xxxxx
	USA, Europe	B461-14	L119310xxxx
	USA	B461-15	J08310xxxxx
	USA, Asia	B461-17	J08310xxxxx
	Europe	B461-22	J08310xxxxx
	Europe	B461-24	L119310xxxx
	Europe	B461-26	4M9103xxxx
	Europe, etc	B461-27	J08310xxxxx