

Model: Stinger-C1 Printer Option		Date: 19-May-00	No.: MB305001
Modified Article: Hard disk change		Prepared by: K. Miura	
From: Technical Services Dept., GTS Division			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction	<input type="checkbox"/> Vendor change	<input type="checkbox"/> To meet standards ()
	<input type="checkbox"/> To facilitate assembly	<input type="checkbox"/> To improve reliability	
	<input type="checkbox"/> Part standardization	<input checked="" type="checkbox"/> Other	

The production of the current 1.6MB hard disk unit was discontinued in March 2000 and the new 6.0GB hard disk has been produced since April 2000.
For the details, please refer to RTB RA250022 / RB001005.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G6905714	G6905718	PCB HDD – 6GB	1	X/O	5	1	
A8537000	B3497000	HDD – MK6014MAP	1	X/O	5	2	

Model: Stinger-C1 Printer Option		Date: 29-May-00	No.: MB305002
Modified Article: Parts catalog correction		Prepared by: K. Miura	
From: Technical Services Dept., GTS Division			
Reason for Modification:	<input checked="" type="checkbox"/> Parts catalog correction	<input type="checkbox"/> Vendor change	<input type="checkbox"/> To meet standards ()
	<input type="checkbox"/> To facilitate assembly	<input type="checkbox"/> To improve reliability	
	<input type="checkbox"/> Part standardization	<input type="checkbox"/> Other	

Please correct your parts catalog as follows:

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
	B3058617	Operating Instructions – Printer (NA)	1		3	20	
	B3058626	Operating Instructions – Taiwanese	1		3	20	
	B3058625	Operating Instructions – Chinese	1		3	20	

Model: Stinger-C1 Printer Option		Date: 19-Sep-00	No.: MB305003
Modified Article: Operating Instructions		Prepared by: K. Miura	
From: Technical Services Dept., GTS Division			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Part standardization	<input type="checkbox"/> Vendor change <input type="checkbox"/> To improve reliability <input checked="" type="checkbox"/> Other	<input type="checkbox"/> To meet standards ()

The information for the Stinger-C1L has been added to the English Operating Instructions.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B3058617	B3058717	Operating Instructions – English	1	X/O	3	20	

Reissued: 25-Oct-00

Model: Stinger-C1 Printer Option	Date: 19-Sep-00	No.: MB305004a
----------------------------------	-----------------	----------------

MB Correction

The items in bold italics have been corrected or added.

Modified Article: Operating Instructions for China/Taiwan		Prepared by: K. Miura	
From: Technical Services Dept., GTS Division			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction	<input type="checkbox"/> Vendor change	<input type="checkbox"/> To meet standards ()
	<input type="checkbox"/> To facilitate assembly	<input type="checkbox"/> To improve reliability	
	<input type="checkbox"/> Part standardization	<input checked="" type="checkbox"/> Other	


The part numbers for the following operating instructions have been changed, in accordance with a request from the division that produces the instructions (Design Division).

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
<i>B3058625</i>	<i>B3058655</i>	Operating Instructions - Chinese	1	X/O	3	20	
B3058626	B3058656	Operating Instructions - Taiwanese	1	X/O	3	20	

Model: Stinger-C1 Printer Option		Date: 15-Mar-02	No.: MB305005
Modified Article: Hard disk change		Prepared by: K. Miura	
From: Technical Services Dept., GTS Division			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction	<input type="checkbox"/> Vendor change	<input type="checkbox"/> To meet standards ()
	<input type="checkbox"/> To facilitate assembly	<input type="checkbox"/> To improve reliability	
	<input type="checkbox"/> Part standardization	<input checked="" type="checkbox"/> Other	

The 6GB Hard Disk Unit has been discontinued from production and replaced with a new 10GB Hard Disk.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G6905718		PCB HDD - 6GB	1		5	1	
	G6905731	PCB HDD - 10GB	1	O/O	5	1	
B3497000		HDD - MK6014MAP	1		5	2	
	G6907000	HDD - MK1016GAP	1	O/O	5	2	



Model: Stinger-C1 Printer Option		Date: 22-Nov-02	No.: MB305006
Modified Article: HDD		Prepared by: K. Miura	
From: Technical Services sec. Service Planning Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Part standardization	<input checked="" type="checkbox"/> Vendor change <input type="checkbox"/> To improve reliability <input type="checkbox"/> Other	<input type="checkbox"/> To meet standards ()

The following have been changed due to a vendor change.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G6905718		PCB HDD - 6GB	1	O/O	5	1	
	► G6905731	PCB HDD - 10GB					
B3497000		HDD - MK6014MAP	1	O/O	5	2	
	► G6907000	HDD - MK1016GAP					