

CDX-51/51RF

SONY


SERVICE MANUAL

*US Model
Canadian Model
AEP Model
UK Model
E Model*

CORRECTION-1

Correct your service manual as shown below.

 : indicates corrected portion.

Page	INCORRECT				CORRECT			
	<u>Ref. No.</u>	<u>Part No.</u>	<u>Description</u>	<u>Remark</u>	<u>Ref. No.</u>	<u>Part No.</u>	<u>Description</u>	<u>Remark</u>
38	12	X-3364-882-1	ARM (SPRING) ASSY		12	X-3370-157-1	ARM (SPRING 2) ASSY 	

(SPM-97148)