

VESTEL ELEKTRONİK A.Ş ORGANİZE SANAYİ BÖL.MANİSA/ TURKEY	PRODUCT CONTENT CHANGE BULLETIN				REF NO
					UMB - xx
CHANGE REQUEST					
EXPLANATION: 1. BREAKDOWN OF THE TRANSISTORS Q201 AND Q202 (CHANGE: C202, C203, TR201) 2. PRODUREMENT PROBLEM OF THE AUDIO LASER OPTIC OUT (CHANGE: JK001) 3. ESD IMPROVEMENT (CHANGE: L425)					
NOTE: THIS CHANGE BULLETIN WILL APPLY ON THE 11AK28-10 PCB ONLY.					
APPLICATION REQUEST DATE			* IMMEDIATELY <input checked="" type="checkbox"/>	* RUNNING CHANGE <input type="checkbox"/>	
AFFECTED PRODUCTS					ADD. LIST <input type="checkbox"/>
COMPONENTS OUT					
No	PCB Code / Pic. No	VESTEL Code	Description	Position	Amount
1		30015725	PCB 11AK28-7		1
2	11 AK 28-10	30007804	TRF. HORIZONTAL DRIVER AK28	TR 201	1
3	11 AK 28-10	30000074	CAP MKT 100NF 63V J	C 202	1
4	11 AK 28-10	30000315	CAP SMD 220NF 25V Z (0805)	C 203	1
5	11 AK 28-10 DVD'Lİ	30008766	OPTIC AUDIO OUTPUT TOTX176	JK 001	1
6	11 AK 28-10 DVD'Lİ	30000818	RES SMD 1/10W 8.2K J (0805)	R 519	1
7					
8					
9					
10					
COMPONENTS IN					
No	PCB Code / Pic. No	VESTEL Code	Description	Position	Amount
1		30017572	PCB 11AK28-10		1
2	11 AK 28-10	30006743	TRF. HORIZONTAL DRIVER 15AK17-17"	TR 201	1
3	11 AK 28-10	30000106	CAP MKT 47NF 100V J	C 202	1
4	11 AK 28-10	30000099	CAP MKT 33NF 63V J	C 203	1
5	11 AK 28-10	30001971	FERRITE BEAT (805) BLM21A601S	L 425	1
6	11 AK 28-10 DVD'Lİ	30012865	OPTIC AUDIO OUTPUT GP1FA550TZ	JK 001	1
7					
8					
9					
10					
COMPONENT IN		ALTERNATIVES FOR COMPONENTS IN			EXIST <input type="checkbox"/> NOT EXIST <input type="checkbox"/>
		COMPONENT IN	ALTERNATIVE	DIFFERENCE COMP.	
				ADD. LIST <input type="checkbox"/>	
RESPONSIBLE ENGINEER		App. Eng. Manager Approval		FINAL NOTES	
NAME SURNAME / DATE/TIME SIGNATURE		SIGNATURE			