

Tools	Control unit Stop+Go and support with fibre optics		2. Support with fibre optics for extension of control unit Stop + Go
	for: WFE (pneumatic)	for: WFE P (electric)	
FE 25, FE 50 FE 50M, FE 75 FE 80	KHP (5 15 086 99) 	KHE (5 15 076 99) 	KHE / P (5 15 080 99) 
MLR 21FE MLR 20FE	KHP 21 (5 15 078 99) 	KHE 21 (5 15 077 99) 	KHE / P 21 (5 15 082 99) 
WSP 80FE	KHP 80 (5 15 084 99) 	KHE 80 (5 15 083 99) 	KHE / P 80 (5 15 141 99) 