

Abstracts

Constraints To The Optimum Performance And Bandwidth Limitations Of Diplexers Employing Three-port Junctions (Correction)

A. Morini. "Constraints To The Optimum Performance And Bandwidth Limitations Of Diplexers Employing Three-port Junctions (Correction)." 1997 Transactions on Microwave Theory and Techniques 45.5 (May 1997, Part I [T-MTT]): 704-704.

The above paper contains some oversights. The first oversite is that $s_{11} = s_{22}$ for both E-plane and H-plane three-port junctions that have one symmetry plane.

[Return to main document.](#)