



# Inspection Release Note

**IRN Reference Number:**  
**IRN003/WF/I-BA-003/10/4.2.10**

Generating Office: BIE Netherlands	BIE Ref: I-BA-003/10	W.O No / Req No: TBA	Inspector: Wilhelm Fraidl	
Client: PDVSA Services	Location: 2517 JK The Hague	Client P.O Number: 5100077213	Date of Inspection: 04 Feb 2010	
Vendor: Derwick Associates, S.A.	Location: Panama	Vendor Ref Number: M.A 5000525041 M.A 5000495549 M.A 5000525038 M.A 5000653244	Punch List Attached: Yes/No  N/A	
Sub Vendor: Pro Energy / Rolls-Royce / Siemens AG	Location: Siemens Erfurt - Germany	Sub Vendor Ref Number: 12009133, 12009134, 12009551, 12009291	NCR's Issued: N/A NCR's Closed:	
<b>PO Item Number</b>	<b>Qty</b>	<b>QTY Previous Release</b>	<b>QTY This Release</b>	<b>Brief Description of Material</b>

3	4	0	4	2-Pole Generator type Siemens SGEN6-100A-2P # 12009133, 12009134, 12009551, 12009291
---	---	---	---	---

<b>Inspectors Signature</b>	Signature W. Fraidl 	Date 04 Feb 2010
<b>BIE Office Review</b>	Signature A.Collings	Date 08 Feb 2010

Any material released above, is for shipment to the designated destination subject to the purchaser's shipping instruction. It does not constitute an acceptance thereof and does not relieve the Vendor, Manufacturer or Contractor of any and all responsibility or obligation imposed by the purchase contract. It does not waive any rights the purchaser may have under the purchase contract including the purchaser's right to reject the above described material upon discovery of any deviations from requirements of the purchase contract, drawings and specifications after arrival at destination.